Uall T	Eicket Number:	ZI416/BR100			
	Texet Number:				
	IV/IV B.Tech (Regular/Supplementary) DEGREE EXAMINATION				
Sevent Time: Ti Answer Q	Deer, 2016 Automation Three Hours Question no. 1 Compulsorily ONE question from each unit Inswer the following What is the difference between gauge pressure and absolute pressure? What is the function of pressure regulator? I psi equal to how many kPa? How do you represent the symbol for shuttle valve in hydraulic/pneumatic circuits? Write the symbol for pilot operated check valve? Define stroke length? What is meterout speed control? Define hysteresis property of a sensor? Define the smart sensor? Define nonlinearity error? Write any two advantages of PLC in industry?				
1.	Write the ladder logic for the following digital logic operation $Y AB + \overline{AB}$ UNIT - I				
2. a.	Define the following terms i. Force ii. Power iii. Torque	6M			
b.	A mass is to be lifted to height by using hydraulic jack. Calculate the diameter of the piston at the narrow end of the system for the specifications given below and also find the displacement if the area of the piston is doubled at the narrow end of the system. A2=1200 cm ² S ₂ 0.5cm	6M			

(OR)

Explain the working of external and internal gear pumps with a neat diagram? Explain and compare full flow filter with proportional flow filter?

6M

UNIT - II

Explain the following valves with neat diagrams.

6M

6M

- i. Fast exhaust valve
- ii. Time delay valve
- Explain the operation of 4 way spool valve with a neat diagram.

6M

(OR) Write about rotary actuators?

6M

Explain different methods of controlling the speed of actuator with a neat diagram?

6M

UNIT - III

- Explain the following. 6. a.
 - Displacement sensors i.
 - Velocity sensor ii.
 - b. What is the nonlinearity error, as percentage of full range, produced when $1k\Omega$ potentiometer has a load of $10k\Omega$ and is at one third of its maximum displacement?


Ī	b.	Explain the following i. Hall effect sensors ii. Temperature sensors	6M
		ii. Temperature sensors	
		UNIT - IV	
8.	a	Explain the basic structure of PLC clearly?	8M
1	b.	Write Ladder logic to generate a square wave with 10% duty cycle.	4M
		(OR)	
9.	a.	Explain about timers and counters in PLC?	7M
1	b.	Device system and write the ladder logic using a PLC, which can be used to control the movement of the piston in a cylinder using a 4/2 solenoid operated valve. The piston is to move in one direction when a proximity sensor at one end of the stroke closes the contacts and in the other direction when a proximity sensor at the other end of the stroke indicated its arrival there.	5M

Scheme of Evaluation


Answer all questions

- 1. a. Pressure measured against the atmospheric pressure is known as gauge pressure.


 1M
 Pressure measured against vacuum is known as absolute pressure.
 - b. The function of the pressure regulator is to maintain the constant pressure to the loads regardless of flow. 1M Generally the input pressure is high compared to the load pressure to maintain constant pressure to the varying loads..
 - c. 1 pound per square inch(psi) = 6.895 kPa (kilo pascals) 1M
 - d. symbol for shuttle valve is
 - e. Symbol for pilot operated check valve is ----- 1M
 - f. The maximum displacement of the piston in the cylinder or the full travel of the piston along the cylinder is known as stroke length.
 - g. Meter out speed control: the control mechanism is placed at the load of the system is known as meter out speed control



h. **Hysteresis**: The deviation of the sensor's output at any given point when approached from two different directions is known as hysteresis.




- i. A smart sensor is a device which consists of built-in signal conditioning circuits and microcontrollers to process the data and present the data in a required format for further control operations.
- j. Non linearity error is defined as the maximum difference from the straight line curve to the actual 1M measured values. It the difference in determining the straight relationship from the actual curve. It is represented as a percentage of the full range output.



- 1. It is known as industrial terminal
- Programming is simple with PLC
- 3. It can handle different kinds of devices
- 4. It is very rugged in its operation.

1.



1M

2M

2M

UNIT - I

2. a. Force: when a force applied on a mass produces acceleration or deceleration which is directly proportional 2M to it

F = ma.

In hydraulic and pneumatic the forces present are due the movement of mass is against the direction or towards the direction of gravitational pull and it is referred as weight. Therefore weight depends on the force of gravity.

The units of force in CGS is dynes, MKS are Newtons, FPS are lbs

1 kgf one kg force produces an acceleration of 9.8m/sec².

Hence 1Kgf = 9.8N etc.

Power: it is defined as the rate at which the work is done

P = work / time

$$P = \frac{W}{T} jouls / \sec or$$
 Watts.

SI unit of power watt and is equal to 1Jouls/sec,

Imperial system uses the horse power (Hp) and is defined as 550lbf/sec.

One horse power is equal to 746W


Torque: is also known as moment of force: it is the tendency of the force to rotate an object around the axis or pivot.

It is known as twist of an object.

It is the cross product of Force and distance.

It is the measure of turning force on an object

The magnitude of the torque depends on the force applied and the length of the lever connecting the axis to the point of force application and the angle between the force and the lever vector.



The SI unit for torque is the Newton-Metre (N-m).

b.
$$A_1 = ?$$

 $S_1 = 15$ cm

 $A_2 = 1200 \text{cm}^2$

 $S_2 = 0.5$ cm

W = 1500 Kg.

 $G = 9.8 \text{m/sec}^2 \text{ or } 10 \text{m/sec}^2$

$$A_1S_1 = A_2S_2$$

$$A_1 = A_2S_2/S_1 = 1200*0.5 / 15 = 40cm^2$$

The diameter of the cylinder is 'd'

HINT: volume displacement on both sides of the cylinder is equal.

Then $\pi d^2/4 = 40 \text{cm}^2$

Implies d = 7.14cm

Area of the piston is doubled then

Then $A1 = 80 \text{cm}^2$;

S1 = 15cm

 $A2 = 1200 \text{cm}^2$

S2 = A1S1/A2 = 80*15/1200 = 1cm

The displacement is 1cm.

3M

3M


(or)

3. a. **External gear pump**: it is positive displacement pump having two moving parts called gear wheels. These moving parts are rotating at a constant speed and thus experiences constant force.

It consists of just two close meshing gear wheels which rotate as shown below. The direction of rotation of the gears is opposite to each other.

As the teeth come out of the mesh at the centre a partial vacuum is formed which draws fluid into the inlet chamber.

Fluid is trapped between the outer teeth and the pump housing. Thus continuous transfer of fluid from inlet chamber to the outlet chamber takes place and thus discharges to the system.



1M

Pump displacement is determined by volume of fluid between each pair of teeth; number of teeth; and speed of rotation.

It delivers fixed volume of fluid is delivered from the inlet port to the outlet port.


Performance of any pump is limited by leakage and the ability of the pump to withstand the pressure differential between inlet and outlet ports.

The gear pump requires closely meshing gears, minimum clearance between teeth and housing, and also between the gear face and side plates.

Wear in a gear pump is primarily caused by dirt particles in the hydraulic fluid, so cleanliness and filtration are particularly important.

Gear pumps are used at pressures up to about 150 bar Volumetric efficiency of gear pumps at 90%

Internal gear pump is constructed in such a way that an extremely driven gear wheel is connected to a smaller internal gear, with fluid separation as gears disengage being performed by a crescent -shaped moulding.



1M

Working principle is same as that of the external gear pumps.

The efficiencies are smaller when compared with the external gear pumps.

They operate at low capacities and the efficiencies are lower compared that of external gear pumps.

b. **Full flow filter:** 2M


All flow passes through the filter as shown in the figure.

It is efficient in terms of filtration.

It incurs a large pressure drop.

This pressure drop increases as the filter becomes polluted, so a full flow filter usually incorporates a relief valve which cracks when the filter becomes unacceptably blocked.

The filter should have been changed before this state was reached as dirty unfiltered fluid would be passing round the system.




Proportional flow filter:

2M

The main flow passes through a venturi, creating a localised low pressure area.

The pressure differential across the filter element draws a proportion of the fluid through the filter. This design is accordingly known as a proportional flow filter, as only a proportion of the main flow is filtered

It is characterized by a low pressure drop, and does not need the protection of a pressure relief valve. Pressure drop across the filter element is an accurate indication of its cleanliness, and many filters incorporate a differential pressure meter



Comparison

2M

Full flow filters:

- 1. It incurs a large pressure drop.
- 2. pressure drop increases as the filter becomes polluted
- 3. It is efficient in terms of filtration.

Proportional flow filters:

- 1. It is characterized by a low pressure drop
- 2. does not need the protection of a pressure relief valve
- 3. Pressure drop across the filter element is an accurate indication of its cleanliness

UNIT – II


4. a. Fast exhaust valve:

2M

A fast exhaust valve is used to vent cylinders quickly.


It consists of a movable disc which allows port A to be connected to pressure port P or large exhaust port R.

It acts like a shuttle valve and has the same symbol.





Fast exhaust valves are usually mounted local to, or directly onto cylinders and speed up response by avoiding any delay from return pipes and control valves.



Time delay valve: 3M

Time delay valves are used to delay operations where time-based sequences are required. The construction of a typical valve is shown below.

This is similar in construction to a 3/2 way pilot-operated valve, but the space above the main valve is comparatively large and pilot air is only allowed in via a flow reducing needle valve.

There is thus a time delay between application of pilot pressure to port Z and the valve operation.


The time delay is adjusted by the needle valve setting.

The built-in check valve causes the reservoir space above the valve to vent quickly when pressure at Z is removed to give no delay off.

The valve is a normally-closed delay-on valve.

All time delay valves i.e. (delay-off, delay on/off, normally-open) can be obtained and all use the basic principle of the air reservoir and needle valve.


The constructional features of time delay valve.



Timing diagram of time delay valve:



The symbol of time delay valve:



b. 4 way spool valve construction & function :

Spool valves are constructed with a spool moving horizontally within the valve body, as shown in the figure for the 4/2 valve

Raised areas called 'lands' block or open ports to give the required operation.

The operation of a spool valve is generally balanced.


There is no net force on the spool from system pressure, allowing the spool to be easily moved.


Spool valves generally have the same body construction, the only difference being the size and position of lands on the spool. T


his is a major cost-saving advantage of spool valves; different operations can be achieved with a common body and different spools.

2M

4 way spool valve:







(OR)

5. a. Rotary actuators:

Rotary actuators are the hydraulic or pneumatic equivalents of electric motors.

For a given torque, or power, a rotary actuator is more compact than an equivalent motor, cannot be damaged by an indefinite stall and can safely be used in an explosive atmosphere.

A rotary actuator can be defined in terms of the torque.

The torque of a rotary actuator can be specified in three ways.


Starting torque is the torque available to move a load from rest.


Stall torque must be applied by the load to bring a running actuator to rest.

Running torque is the torque available at any given speed.


Running torque falls with increasing speed,

torque is dependent on the applied pressure; increasing the pressure results in increased torque, as shown.





The running torque falls with increasing speed, so the relationship between power and speed has the form of Figure shown below with maximum power at some (defined) speed. Power like the torque, is dependent on applied pressure.



Power/speed curve for pneumatic rotary actuator

The torque produced by a rotary actuator is directly related to fluid pressure; increasing pressure increases maximum available torque. Actuators are often specified by their torque rating,

Torquerating Torque

Rotational speed is given by:

Rotational speed Rotational speed $\frac{fl}{dt}$

fluid flow rate displacement

With the torque rate and displacement fixed for a chosen motor, the user can control maximum available torque and speed by adjusting, respectively, pressure setting and flow rate of fluid to the actuator. maintenance

- b. Speed control actuator:
 - 1. Speed control by pump volume

(any three methods 2M for each method)

- 2. Meterin speed control
- 3. Meterout speed control
- 4. Bleed off speed control.


2M

Speed control by pump volume:

Pump delivers a fluid volume V per minute. Because the pump is a fixed displacement device this volume of fluid *must* go either back to the tank or to the actuator. When the control valve moves from its centre position, the actuator moves with a velocity:

$$v = \frac{V}{A} \text{m/s}$$

Where A is the piston area. If pump delivery volume V can be adjusted by altering swash plate angle *and* the pump feeds no other device, no further speed control is needed.




2M

Meter in speed control:

If a pump controls many devices and is loaded by a solenoid-operated valve. Unused fluid goes back to the tank via relief valve V 3. The pump output is higher than needed by any individual actuator, so a flow restrictor is used to set the flow to each actuator. This is known as a 'meter in' circuit, and is used where a force is needed to move a load.


Check valve V 1 gives a full-speed retraction, and check valve V 2 provides a small back pressure to avoid the load running away. The full pump delivery is produced when the pressure reaches the setting of relief valve V 3, so there is a waste of energy and unnecessary production of heat in the fluid.



Meter out speed control:

2M

If the load can run away from the actuator, the third speed control method; the 'meter out' circuit must be used. This method again gives a controlled extension speed, and full retraction speed. As before, the pump delivers fluid at a pressure set by the relief valve, leading to heat generation.




2M

2M

This speed control method bleed-off valve V 1 is incorporated. This returns a volume v back the tank, leaving a volume V-v to go to the actuator where V is the pump delivery volume. Pump pressure is now determined by the required actuator pressure, which is lower than the pressure set on the relief valve. The energy used by the pump is lower, and less heat is generated. The circuit can, however, only be used with a load which opposes motion. Check valve V 2 again gives a small back pressure.

Any unused fluid from the pump is returned to the tank at high pressure leading to wasted energy; even with the more efficient 'bleed'-off circuit. One moral, therefore, is to have a pump delivery volume no larger than necessary.




UNIT - III

6. a. Displacement sensor:

1. Potentiometer sensor

Derive he expression fo nonlinearity error for the potentiometer under load




Nonlinearity error % = $\frac{R_p}{R_L} (x^2 - x^3)$

2. Strain gauge

The electrical strain gauge is a metal wire of semiconductor material which is a wafer like and that can be struck on to the surface.

When subjected to strain the résistance of the foil changes and is directly proportional to the strain.



 $\frac{\Delta R}{R}$ $G\varepsilon$ G is the gauge factor and ε is known as strain.

The strain gauge is inserted in the bridge network for the measurement purposes.

3. Capacitive sensor

The capacitance of A parallel plate capacitance is given by


$$C \quad \frac{\varepsilon_0 \varepsilon_r A}{d}$$

 \mathcal{E}_r Is the relative permittivity


 \mathcal{E}_0 Permittivity of the free space

If a change in the distance of the parallel plates is 'x' then


Change in the capacitance is given by $C - \Delta C = \frac{\varepsilon_0 \varepsilon_r d}{d + x}$



LVDT sensor(differential transformer)



Induced e.m.f. ios given by e $M \frac{di}{dt}$ Output voltage $= -(k_1-k_2)sin(\omega t-\phi) = (k_2-k_1)sin[\omega t+(\pi-\phi)]$



Velocity sensor:


Encoders: incremental encoder, absolute encoders

Incremental encder provides a digital output as a result of linear or angular displacement. The beam of light passes through slots in the disk an disc detected by a suitable sensor.

2M

2M


Number pulses generated within the specified time will be proportional to the velocity or rpm of the disc. Thus we can find the velocity.



Techogenerator:

It is used to measure the angular velocity. The variable reluctance tachogenerator consists of toothed wheel of ferromagnetic material which is attached to the rotating shaft pickup coil is wound on the permanent magnet. As the wheel rotated so the teeth move past the coil and the air gap between the coil and the ferromagnetic material changes. The resulting cyclic change in the flux linked produces an

alternating e.m.f. in the coil e $N\Phi n\omega \sin(\omega t)$



b. Problem:

Load resistance of = $10K\Omega$

Potentiometer resistance = $1k\Omega$

Rati of displacement = x = 1/3;

Non linearity error = $\frac{R_p}{R_L} (x^2 - x^3)$ = $\frac{1}{10} ((1/3)^2 - (1/3)^3) x 100$ = 0.74%

(OR)

7. a. Sensor parameters:

Range and span: the range of a sensor is defined as the limits between which the input can vary.

 $Span = maximum \ value - minimum \ vales$


Error: it is defined as the difference between the result of measurement and the true value of the quantity Error = measured value – true vale

Accuracy: it is the percentage of the full range output or the full scale deflection


Sensitivity: it is defined as the change in the output for a small change in the input.

Hysteresis: The deviation of the sensor's output at any given point when approached from two different directions is known as hysteresis

4M



Nonlinearity error: Non – linearity error is defined as the maximum difference from the straight line curve to the actual measured values. It the difference in determining the straight relationship from the actual curve. It is represented as a percentage of the full range output.



Repeatability: it is the ability of the transducer to give same output for repeated application of the same input value.

Repeatability: (max – min value given)/ full range * 100

Stability: it is the ability to give same output when used to measure a constant input over a period of time.

Dead band/time: range of input values for which there is no output

Output impedance


Static characteristics:

Dynamic characteristics: time constant, rise time, settling time etc.

b. **Hall effect sensor:** when a beam of charged particles passes through a magnetic field, forces act on the particles and the beam is deflected from its straight line path. A current flowing I a conductor is like beam of moving charges and they can be deflected by magnetic field. This effect is known as Hall effect.



3M



As consequence of the magnetic fields the moving electrons are deflected to one side of the palte and thus that side becomes negatively charges while the opposite side becomes positively charged . this charge separation produces an electric field in the material. The result is a transverse potential difference V is give as

$$V K_H \frac{BI}{t}$$

Hall effect sensors generally manufactured with integrated circuit and necessary circuitary to produce sufficient voltage.

There are two basic forms of 1. Linear sensor 2. Proximity sensor.

Linear hall effect sensors switch from o volts to 140mv when the magnetic field is about 3mT.

These sensors can be operated as switches also and they can be operated up to 100KHz repetition rate.

They are immune to environmental effects also.

They are used as position, displacement and proximity sensors.

Temperature sensors:

Bi metallic strips:

The device consists of two different metal strips bonded together. The metals have different thermal expansion coefficients. When the temperature changes the composite strip bends into curved strip with the higher coefficient mental on the outside of the curve.

Resistance temperature detectors:

The resistance of the metals increases over the limited temperature range in a linear way with the increase in the temperature.

$$R_t R_o(1+\alpha t)$$

Where R_t is resistance of the material at temperature t α is constant and is termed as temperature coefficient.

<u>Thermistors:</u> These are small pieces of metal made from mixture of metal oxides. (chromium, iron, manganese, and nickel).

Thermistors have negative temperature coefficient and is given by

$$R_t Ke^{\beta/t}$$

Thermistors respond very rapidly to the changes in the temperature and small in size and hence they can be used effectively in the industry.


<u>Thermo couples:</u> Two different metals are joined together. The potential difference depends on the metals used and the temperature of junction.

If both the junctions are maintained at the same temperature then the net e.m.f. is zero. The value of the e.m.f. depends on the two metals connected and the temperature 't'.

$$E \quad at + bt^2$$

UNI T – IV

8. a. Basic structure of PLC:



The CPU:

2M

The internal structure of the CPU depends on the microprocessor used.

- 1 An *arithmetic and logic unit* (ALU) which is responsible for data manipulation and carrying out arithmetic operations of addition and subtraction and logic operations of AND, OR, NOT and EXCLUSIVE-OR.
- 2 Memory, termed *registers*, located within the microprocessor and used to store information involved in program execution.
- 3 A *control unit* which is used to control the timing of operations.

The buses:

- 1. The *data bus* carries the data used in the processing carried out by the CPU. A microprocessor termed as being 8-bit has an internal data bus which can handle 8-bit numbers. It can thus perform operations between 8-bit numbers and deliver results as 8-bit values.
- 2. The *address bus* is used to carry the addresses of memory locations. So that each word can be located in the memory, every memory location is given a unique *address*. Just like houses in a town are each given a distinct address so that they can be located, so each word location is given an address so that data stored at a particular location can be accessed by the CPU either to read data located there or put, i.e. write, data there.
- 3. The *control bus* carries the signals used by the CPU for control, e.g. to inform memory devices whether they are to receive data from an input or output data and to carry timing signals used to

2M

- synchronise actions.
- 4. The *system bus* is used for communications between the input/outputports and the input/output unit.

The Memory:

1. System *read-only-memory* (*ROM*) to give permanent storage for the operating system and fixed data used by the CPU.

Random-access memory (RAM) for the user's program.

3. Random-access memory (RAM) for data. This is where information is stored on the status of input and output devices and the values of timers and counters and other internal devices.

Input/output unit:

The input/output unit provides the interface between the system and the outside world, allowing for connections to be made through input/output channels to input devices such as sensors and output devices such as motors and solenoids. It is also through the input/output unit that programs are entered from a program panel.


Every input/output point has a unique address which can be used by the CPU.

The input/output channels provide isolation and signal conditioning functions so that sensors and actuators can often be directly connected to them without the need for other circuitry.

Electrical isolation from the external world is usually by means of *optoisolators*.

When a digital pulse passes through the light-emitting diode, a pulse of infrared radiation is produced. This pulse is detected by the phototransistor and gives rise to a voltage in that circuit. The gap between the light-emitting diode and the phototransistor gives electrical isolation. but the arrangement still allows for a digital pulse in one circuit to give rise to a digital pulse in another circuit.

b. Write Ladder logic to generate a square wave with 10% duty cycle.



On time = 10 sec and off time = 90sec Duty cycle = 10%

(OR)

9. a. Timers:

In many control tasks there is a need to control time. For example, a motor or a pump might need to be controlled to operate for a particular interval of time, or perhaps be switched on after some time interval. PLCs thus have timers as built-in devices. Timers count fractions of seconds or seconds using the internal CPU clock. The timers can be programmed to carry out control tasks.


- 1. Delay on timers
- 2. Off delay timers

2M


4M

3. Pulse timers

The following figure shows the typical diagram for the three timers



The following are the representation of timers.




IEC 1131-1 standards. BOOL indicates a Boolean input/output, i.e. on/off. IN is the input. Q is the output. ET is the elapsed time output. PT is the input used to specify the time.

The time duration for which a timer has been set is termed the preset and is set in multiples of the time base used. Some time bases are typically 10 ms, 100 ms, 1 s, 10 s and 100 s. Thus a preset value of 5 with a time base of 100 ms is a time of 500 ms.

Counters:

Counters are provided as built-in elements in PLCs and allow the number of occurrences of input signals to be counted. This might be where items have to be counted as they pass along a conveyor belt, or the number of revolutions of a shaft, or perhaps the number of people passing through a door. This chapter describes how such counters can be programmed.

A counter is set to some preset number value and, when this value of input pulses has been received, it will operate its contacts.



Down-counters count down from the present value to zero, i.e. events are subtracted from the set value. When the counter reaches the zero value, its contacts change state.


Up-counters count from zero up to the preset value, i.e. events are added until the number reaches the preset value. When the counter reaches the set value, its contacts change state.

PLC manufacturers deal with counters in slightly different ways. Some countdown (CTD), or up (CTU), and reset and treat the counter as though it is a relay coil and so a rung output.

Counters can consist of two basic elements: one relay coil to count input pulses and one to reset the counter, the associated contacts of the counter being used in other rungs. The above figure illustrates this.

b. Device system and write the ladder logic using a PLC, which can be used to control the movement of the piston in a cylinder using a 4/2 solenoid operated valve. The piston is to move in one direction when a proximity sensor at one end of the stroke closes the contacts and in the other direction when a proximity sensor at the other end of the stroke indicated its arrival there.

2M



The system specifications

V1 is a 4/2 valve

'a' is NO switch which closes on detecting s1 signal

When a closes then solenoid y1 is activated and the spool will move forward.

When the proximity sensor detects the cylinder then it gives control signal to contact 'b' to glow the light.

The stop signal is use to stop the entire operation.

T refers to tank.

S refers to sump.